

The Boeing Company
P.O. Box 3707
Seattle, WA 98124-2207

MAR 21 2008

B-H210-08-00232

Docket Management Facility
U.S. Department of Transportation
400 Seventh Street SW
Nassif Building, Room PL-401
Washington, DC 20590
Attention: Airworthiness Rules Docket No. FAA-2007-27824




BOEING

Subject: Comments, IAR Docket No. FAA-2007-27824, Directorate Identifier 2003-NE-12-AD, "Relaxes the Removal Compliance Time for Certain Disc Assemblies That Have a Record of Detailed Inspections", Airplane Models 747, 757, and 767

Boeing has reviewed the subject NPRM and concurs with the contents of the proposed rule. Therefore, no additional comments will be forthcoming.

Very truly yours,



J. R. Murphy
Manager, Continued Airworthiness
Twin Aisle Programs
B-H210, M/C 0A-87, (425) 965-3626
FAX: (425) 342-5219

smb